

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/25/2019

Submitted Date:

06/25/2019

Document Number:

692602066**FIELD INSPECTION FORM**
 Loc ID 337735 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 55575Name of Operator: MCELVAIN ENERGY INCAddress: 511 16TH STREET SUITE 700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Cooper, Tony	(303) 893-0933 x331	tony.cooper@mcelvain.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288369	WELL	PR	09/30/2007	GW	125-10540	RAVEN 3-10	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by VGS		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, meter shed, metal shed and VGS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry equipment, gas scrubber and chemical tank w/containment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit. Horsehead and bridle removed at time of inspection		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	1-Vertical gas separator 50% buried by meter run 1-Vertical gas separator in metal shed		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288369	Type:	WELL	API Number:	125-10540	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Downhole equipment removed from wellbore and free flowing at time of inspection								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT