

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/25/2019

Submitted Date:

06/25/2019

Document Number:

692602071**FIELD INSPECTION FORM**

Loc ID 337834 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 55575Name of Operator: MCELVAIN ENERGY INCAddress: 511 16TH STREET SUITE 700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Cooper, Tony	(303) 893-0933 x331	tony.cooper@mcelvain.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288902	WELL	PR	09/30/2008	GW	125-10644	FALCON 35-15	PR

General Comment:Routine Inspection

Location				
Lease Road:				
Type	Access			
comment:	Dirt road through pasture			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	CONTAINERS			
Comment:	Stickers on chemical tank			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Lease sign by VGS			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal panels around unit, wellhead, meter shed, metal shed and VGS			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Pump Jack	# 1			
Comment:	Churchill unit. Horsehead and bridle removed from unit			
Corrective Action:				Date:
Type: Vertical Separator	# 2			
Comment:	1-Vertical gas separator 50% buried by meter run 1-Vertical gas separator in metal shed			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Telemetry equipment, gas scrubber and chemical tank w/containment			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:

Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288902	Type:	WELL	API Number:	125-10644	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Downhole equipment removed from wellbore at time of inspection and free flowing								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT