

Laramie Energy LLC  
API # 05-077-10250  
Inspection # 696600175




Photo #1 Photo from entrance of location.

Photo #2 Photo from entrance of location.

Laramie Energy LLC  
API # 05-077-10250  
Inspection # 696600175



Photo #3 Photo of tank Battery. Tank labels on bank side of tanks up against hill side



Photo #4 Photo of Wellheads

Laramie Energy LLC  
API # 05-077-10250  
Inspection # 696600175



**Photo #5 BMP's damaged and not maintained at the SW side of location . Berm damaged**

**Photo #6 BMP's damaged and not maintained at the SW side of location. Berm damaged Erosion shown of location**

Laramie Energy LLC  
API # 05-077-10250  
Inspection # 696600175



**Photo #7 SW side of location BMP is damaged. Berms around location have been constructed as storm water BMP, with no stabilization, and damage.**