

**Inspection Photos**  
**Location Name: Hosmer 21-32**  
**Location ID: 320079**



**Pic 1**



**Pic 2 unused equipment in motor house of pumping unit**

**Inspection Photos**  
**Location Name: Hosmer 21-32**  
**Location ID: 320079**



**Pic 3 unused equipment in motor house of pumping unit**



**Pic 4 stained soil inside motor house of pumping unit**

**Inspection Photos**  
**Location Name: Hosmer 21-32**  
**Location ID: 320079**



**Pic 5 chemical tank with no containment/unused equipment**



**Pic 6 tubing and part of motor house on location**

**Inspection Photos**  
**Location Name: Hosmer 21-32**  
**Location ID: 320079**



**Pic 7 metal sheeting from motor house**



**Pic 8 unused piping, and tubing**