

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871



Pic 1



Pic 2 stained soil

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871



Pic 3 stained soil



Pic 4

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871



Pic 5 weeds uncontrolled



Pic 6 weeds uncontrolled

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871



Pic 7



Pic 8 weeds uncontrolled

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871




Pic 9 possible leak stained soil



Pic 10 possible leak on bottom of tank

Inspection Photos
Location Name: Wenzel-Hosmer 4-4
Location ID: 319871



Pic 11 possible leak



Pic 12 weeds on location