

WELL SITE INSPECTION FORM



WELL NAME Apache Cuy 11-7
OPERATOR Meridian Oil Inc
LOCATION SWNE 11-345 68W
FIELD _____

API NUMBER 05 - 071 - 05020
PERMIT NUMBER 890685
COUNTY Las Animas
INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) _____ DATE 6-6-90 WELL STATUS: FN ☒ FD _____ WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS This well is DA Continental Well.
has dry hole marker intact. Not re-entered.

