

Caerus Piceance LLC
API # 05-077-10163
Inspection # 696600195



Photo #1 Photo from Entrance of location
Sign missing information.



Photo #2 Photo from Entrance of location

Caerus Piceance LLC
API # 05-077-10163
Inspection # 696600195



Photo # 3 Photo of tank Battery



Photo # 4 Photo of Wellheads.

Caerus Piceance LLC
API # 05-077-10163
Inspection # 696600195



Photo # 5 Unused equipment stored on location



Photo # 6 Unused equipment stored on location

Caerus Piceance LLC
API # 05-077-10163
Inspection # 696600195



Photo # 7 Unused equipment stored on location
Pipe fittings and ladder, black plastic pipe.



Photo # 8 Unused equipment stored on location
Stairs and tarp.