

# Interim Reclamation and Stormwater Inspection

June 25, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 458702

Inspection Document #: 697500247

Weld County, CO

NENE Section 7 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 1.** Photo taken of the northern topsoil stockpile, facing North. Photo illustrates the Operator has failed to protect the topsoil from erosion and weed establishment. Weeds were approximately 3' tall and erosion was observed throughout the stockpile.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 2.** Photo taken from the south-side of the northern topsoil stockpile, facing North.  
See comments under Photo 1.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 3.** Photo taken from the south-side of the northern topsoil stockpile, facing South.  
See comments under Photo 1.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 4.** Photo taken from the west-side of the northern topsoil stockpile, facing South.  
See comments under Photo 1.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 5.** Photo taken of the fill slope of the southern pad, facing South. Photo illustrates the Operator has failed to maintain the location so as to reasonably minimize erosion, and site degradation per Rules 1002.e. and 1002.f.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 6.** Photo taken from the southern pad, facing East. See comments under Photo 5. Photo also illustrates rutting throughout the location which the Operator is tracking off location because there are no vehicle tracking device BMPs at either of the entrances. The vehicle tracking device has only been installed at the intersection of CR 15.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 7.** Photo taken from the southern pad, facing West. See comments under Photo 6.

Inspection Photos  
Location Name: BUDDY /17-7HZ  
Location ID: 458702



**Photo 8.** Photo taken from the northern pad, facing West. See comments under Photo 6.