

Inspection Photos
Location Name: LILLI UNIT-68N59W /12SENE
Location #: 326921



Photo #1
Lilli Unit 8-12 (05-123-13865) UIC - Injection Wellsite
UIC Annual Inspection
Shut-In | SI
Not Injecting



Photo #2
Lilli Unit 8-12 UIC - Injection Well
Shut-In | SI
Not Injecting

Inspection Photos
Location Name: LILLI UNIT-68N59W /12SENE
Location #: 326921



Photo #3
Lilli Unit 8-12 UIC - Injection Well
Tbg. Press: 400#
Shut-In | SI
Not Injecting



Photo #4
Lilli Unit 8-12 UIC - Injection Well
Csg Press: 0#
Shut-In | SI
Not Injecting

Inspection Photos
Location Name: LILLI UNIT-68N59W /12SENE
Location #: 326921



Photo #5
Lilli Unit 8-12 UIC - Injection Well
Bradenhead Press: 0#
Shut-In | SI
Not Injecting