

**Inspection Photos**  
**Location Name: Dyer USX AB 35-68-1HN**  
**Location ID: 426749**



**Photo 1 – Tank Battery**

**Photo 2 – Separators**

**Inspection Photos**  
**Location Name: Dyer USX AB 35-68-1HN**  
**Location ID: 426749**



**Photo 3 – Dyer USX AB 35-68-1HN Pumping Unit**



**Photo 4 – Dyer USX AB 35-67-1HN Pumping Unit**

**Inspection Photos**  
**Location Name: Dyer USX AB 35-68-1HN**  
**Location ID: 426749**



**Photo 5 – Unused Pneumatic Injection Pumps in East Engine house, along South wall**

**Photo 6 – Unused Pneumatic Injection Pumps in East Engine house, along North wall**

**Inspection Photos**  
**Location Name: Dyer USX AB 35-68-1HN**  
**Location ID: 426749**



**Photo 7 – Trash in West Engine house, along West wall**



**Photo 8 – Unused chemical drum in West Engine house, on the North wall**