

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2019

Submitted Date:

06/28/2019

Document Number:

692602081**FIELD INSPECTION FORM**
 Loc ID 321688 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rogers, Bob	719-767-8851	brogers@cogc.com	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207783	WELL	PR	11/29/1989	GW	017-06718	BERGE 31-1 1	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign by treater shed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Stickers on chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Metal panels around water tank		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around treaters		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: <a href="#">Metal panels around oil tanks</a>			
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment: <a href="#">Meter run on north side of treaters</a>			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment: <a href="#">Lufkin 912</a>			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment: <a href="#">2-Treaters w/metal sheds on west side of oil tanks</a>			
Corrective Action:		Date:	
Type: Vertical Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: <a href="#">Electric motor</a>			
Corrective Action:		Date:	
Type: Ancillary equipment	# 6		
Comment: <a href="#">Electric panel, cathodic rectifier, 2-chemical tanks w/containment, circ pump at tanks, electric water transfer pump in metal shed</a>			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.951330,-103.058980
Comment: <a href="#">Tan tank on west side of tank battery location</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLs	STEEL AST		38.951630,-103.058090	
Comment:	Shared tank battery for Berge 31-1 and 22-1					
Corrective Action:					Date:	
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	207783	Type:	WELL	API Number:	017-06718	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (Berge 22-1 & 31-1)								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT