

Interim Reclamation Inspection

June 25, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-09493

Inspection Document #: 697500249

Weld County, CO

SESW Section 21 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: MILTON H. NELSON UNIT B #1

API: 05-123-09493



Photo 1. Photo taken from the well sign, facing West. Operator sign is fading and may need to be replaced in the near future.

Inspection Photos

Location Name: MILTON H. NELSON UNIT B #1

API: 05-123-09493



Photo 2. Photo taken from the western location, facing South. Pumpjack is no longer in use; therefore, Operator shall remove any unused equipment not needed for production operations. Photo also illustrates weeds throughout the entire perimeter of the location that are not being managed.

Inspection Photos

Location Name: MILTON H. NELSON UNIT B #1

API: 05-123-09493



Photo 3. Photo taken from the western location, facing East. Pumpjack is no longer in use and has been gone for at least 9 years; therefore, Operator shall remove the concrete slabs.

Inspection Photos

Location Name: MILTON H. NELSON UNIT B #1

API: 05-123-09493



Photo 4. Close up photo taken of a List B Colorado Noxious weed, Musk thistle, that is not being managed. Operator shall immediately control and manage all noxious weeds.