

Interim Reclamation Inspection

June 25, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-09515

Inspection Document #: 697500251

Weld County, CO

SWNW Section 28 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SERAFINI 'B' #2
API: 05-123-09515



Photo 1. Photo taken from the tank battery sign, facing West.

Inspection Photos
Location Name: SERAFINI 'B' #2
API: 05-123-09515



Photo 2. Photo taken from the tank battery location, facing West. Photo illustrates the Operator has failed to control and manage weeds, some of which are noxious.

Inspection Photos
Location Name: SERAFINI 'B' #2
API: 05-123-09515



Photo 3. Photo taken from the tank battery location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: SERAFINI 'B' #2
API: 05-123-09515



Photo 4. Photo taken from the tank battery location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: SERAFINI 'B' #2
API: 05-123-09515



Photo 5. Photo taken from the northern tank battery location, facing South. See comments under Photo 2. Photo illustrates an used cattle guard.