

Interim Reclamation Inspection

June 25, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-09500

Inspection Document #: 697500253

Weld County, CO

NESE Section 32 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON TRUST #1
API: 05-123-09500



Photo 1. Photo taken from the tank battery sign, facing West.

Inspection Photos
Location Name: ANDERSON TRUST #1
API: 05-123-09500



Photo 2. Photo taken from the tank battery location, facing North. Photo illustrates the Operator has failed to control and manage weeds, some of which are noxious.

Inspection Photos
Location Name: ANDERSON TRUST #1
API: 05-123-09500



Photo 3. Photo taken from the tank battery location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: ANDERSON TRUST #1
API: 05-123-09500



Photo 4. Photo taken from the tank battery location, facing South. See comments under Photo 2. Photo illustrates a List B Colorado Noxious weed, Musk thistle.

Inspection Photos
Location Name: ANDERSON TRUST #1
API: 05-123-09500



Photo 5. Photo taken from the tank battery location, facing South. See comments under Photo 2.