

Inspection Photos
Location Name: Federal 11-90-24 #1
API: 05-051-06057



Concrete pad and gravel stained with oil.



Impacted material from REM #12222 stock piled on location has been removed.

Inspection Photos
Location Name: Federal 11-90-24 #1
API: 05-051-06057



REM #12222 project area has been backfilled.



Project area has been backfilled. Ensure appropriate BMPs are installed to stabilize work area.