

Inspection Photos

Location #334481

Operator: Fram

Inspection #: 692401125

Inspection Date: 6/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

June 21, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#2:
Localized area of stained soil at well head area.



Photo#3:
Localized area of staining at well head area.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#4:
Supplies not stored in secure containment.

June 21, 2019



Photo#5:
Close up of Bucket not in secure containment (contents of which should be disposed of in accordance with 907.e.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#4:
Staining in tank containment.

June 21, 2019



Photo#5:
Supplies not stored properly.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#4:

Various pieces of Debris/Trash on Site.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#5:
Unused equipment stored on site.

June 21, 2019



Photo#6:
Unused equipment stored on site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Siminoe Loc#334481



Photo#7:
View of existing vegetation on peripheries of site.

June 21, 2019



Photo#8:
Noxious Weed, Knapweed on site.