

Maralex Resources Inc.
API # 05-077-08540
Inspection # 696600233



Photo #1 Photo at entrance to location



Photo #2 photo of well head and sign

Maralex Resources Inc.
API # 05-077-08540
Inspection # 696600233



Photo #3 photo of pit



Photo #4 photo of gas meter

Maralex Resources Inc.
API # 05-077-08540
Inspection # 696600233



Photo #5 Unknow



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources