

Inspection Photos

Location Name: Federal RGU 31-24-198

Spill/Release ID: 465418

Inspection Date: June 19, 2019



Photo #1 – Aerial view of the location, white X marks the spill location (GISOnline Maps).



Photo #2 – View of the excavation and stockpiled soil looking north. The ruptured flowline can be seen in the bottom of the excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal RGU 31-24-198
Spill/Release ID: 465418
Inspection Date: June 19, 2019



Photo #3 – View of the dripping plug and the impacted storm water.



Photo #4 – View of the stained pit liner and impacted storm water.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal RGU 31-24-198

Spill/Release ID: 465418

Inspection Date: June 19, 2019



Photo #5 – View of the pen sized hole in one of the 500 BBL produced water tank.



Photo #6 – Sign of the leaking well head.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal RGU 31-24-198

Spill/Release ID: 465418

Inspection Date: June 19, 2019



Photo #7 – View of the leaking well head.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources