

Inspection Photos
Location Name: Shiras CTB S11
Location ID: 451937



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Stained soil and trash at generator.

