

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Example of stained soil on location, this example located at wellhead.



Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 3. Example of trash and debris on location.



Photo 4. Earth berm with no evidence of liner. Condensate tank labeled as crude oil, no capacity on tank label.



Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 5. Example of trash and debris on location.



Photo 6. E & P waste inside triplex jet pump containment.

