

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Frack sand spilled on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 3. All wellheads buried in gravel.



Photo 4. No wellhead visible.



Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 5. Stained gravel, wellhead not visible.

