

**Inspection Photos**  
**Location Name: Hebron Central Facility 434014**  
**Location ID: 434014**



**Photo 1. Overview of location taken at entrance facing west.**



**Photo 2. Frack sand spilled on location.**



**Inspection Photos**  
**Location Name: Hebron Central Facility 434014**  
**Location ID: 434014**



**Photo 3. Spilled frack sand migrating off location.**



**Photo 4. Examples of stained soil on location.**





**Inspection Photos**  
**Location Name: Hebron Central Facility 434014**  
**Location ID: 434014**



**Photo 5. Stained soil with fertilizer.**



**Photo 6. Close up of photo 3.**

