

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 1. Tubing stored on location.



Photo 2. Frack sand spilled on location.



Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 3. Frack sand spilled on location.



Photo 4. Frack sand spilled on location.
Photo from inspection document number 689801879 taken 11/1/2018.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 5. Stormwater in berm with loadout hose resting in water.



Photo 6. Gravel added to washout observed on 5/3/2019.

Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 7. No additional tracking measures observed.



Photo 8. Tracking onto Colorado Highway 14.



Inspection Photos
Location Name: Rabbit Ears 0681 23
Location ID: 449274



Photo 9. Tracking onto Colorad Highway 14.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources