

Inspection Photos
Location Name: Nelson 23-34
Location ID: 306691



Photo 1: Wellhead



Photo 2: Centralized Tank Battery



Inspection Photos
Location Name: Nelson 23-34
Location ID: 306691



Photo 3: Erosion




Photo 4: Erosion



Inspection Photos
Location Name: Nelson 23-34
Location ID: 306691



Photo 5: Erosion south of seperator