

**Inspection Photos**  
**Location Name: Raindance Drill Pad**  
**Location ID: 427917**



**Photo 1: No grounding rod**

