



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Jun 13, 2019 8:45:13 AM MDT
Server Receive Date: Jun 13, 2019 8:46:39 AM MDT
Reference Number: 20190613-18108884895
Location: 557 Airpark Dr, Durango, CO 81303, USA
Jun 13, 2019 8:44:19 AM MDT [[View Map](#)]

Information

Name	colen@horizonenvservices.com
Date	Jun 10, 2019
Well Name	MCDONALD, HC 1
API Number	50670514400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding Erosion Repairs

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

installed rock checks, seeded and hydromulched

