

Maralex Resources Inc.
API # 05-077-08594
Inspection # 696600241



Photo #1 Photo of Tank Battery sign at Tank battery

Photo #2 photo from entrance of location

Maralex Resources Inc.
API # 05-077-08594
Inspection # 696600241



Photo #3 photo of tank battery



Photo #4 photo of Wellhead

Maralex Resources Inc.
API # 05-077-08594
Inspection # 696600241



Photo #5 Weeds and Debris on location



Photo #6 Weeds and Debris on location and in tank battery containment