

Caerus Piceance LLC  
API # 05-077-08483  
Inspection # 696600248



Photo #1 Photo of Unused equipment on location



Photo #2 photo from entrance of location

**Caerus Piceance LLC**  
**API # 05-077-08483**  
**Inspection # 696600248**



**Photo #3 photo of tank battery**



**Photo #4 photo of Wellhead**