

## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



Photo #1 - Facility sign located at gate on east side of location.



Photo #2 - View of tank battery on east side of pad.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



**Photo #3 – Fluid remaining inside of tank battery berm on south side.**



**Photo #4 – Fluids remaining inside of tank battery along east berm.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



**Photo #5 – Compromised sections of tank battery liner along base of containment area, east of tanks.**



**Photo #6 – Saturated area outside of tank battery containment berm on east side.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



**Photo #7 – Compromised section of tank battery liner on east side of battery.**



**Photo #8 – Stained soil located south of tank battery.**



## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



Photo #9 – Chemical storage tanks with secondary containment devices at compressor station (1).



Photo #10 - Chemical storage tanks with secondary containment devices at compressor station (2).



## Inspection Photos

Location Name: Rulison Compressor Station Tank Battery Spill

Spill/Release ID: #465241

Inspection Date: June 24, 2019



**Photo #11 – Unidentified stockpile of impacted soil located at northwest corner of location. Stockpiles contained precipitation with little freeboard (~1”). Stained and saturated soil beneath storage containers indicate that fluids have escaped containment previously (red arrows).**

**Photo #12 – Unused equipment stored in northeast corner of location.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources