

Inspection Photos
Location Name: STATE-66N64W /36NESE
Location #: 327512



Photo #1
State A 36-9 (05-123-14790) Wellsite
Shut-In | SI
Emergency Contact number NOT posted
Delinquent MIT
from prior insp.



Photo #2
State A 36-9 Wellsite
Temporarily Abandoned | TA
Correct Emergency number NOW posted
New Current MIT

Inspection Photos
Location Name: STATE-66N64W /36NESE
Location #: 327512



Photo #3
Devries State A 36-21, 36-23, Scholfield A 36-20,
State A 36-9 - Battery
Shut-down
from prior insp.