

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 1. Access road with fresh material and no stormwater BMPs.



Photo 2. Access road with fresh material and no stormwater BMPs.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 3. Stained soil in tank removal area migrating out of work area.



Photo 4. Free product and stained soil and plastic tarping becoming debris in tank removal area.



Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 5. Example of free product in equipment containment.



Photo 6. Example of free product in equipment containment.



Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 7. Example of free product in equipment containment.



Photo 8. Example of stained soil on location.



Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 9. Example of free product drips in equipment without containment.



Photo 10. Example of drip with nearly full pan underneath.



Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 11. Example of drip with nearly full bucket underneath and stained soil and free product around on equipment without containment.



Photo 12. Example of bucket of oily waste not in containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 13. Area of stained soil from previous inspection behind equipment shed. Stained soil has been removed, bucket for drips located outside shed.



Photo 14. Close up of bucket contents and no containment from photo 13.

