

Laramie Energy LLC
API # 05-077-08463
Inspection # 6966002450



Photo #1 Photo of Battery Sign at entrance to location



Photo #2 Photo from entrance of location

Laramie Energy LLC
API # 05-077-08463
Inspection # 6966002450



Photo #3 photo of Wellhead



Photo #4 Photo at Wellhead. Bubbles coming from around wellhead inside of cellar

Laramie Energy LLC
API # 05-077-08463
Inspection # 6966002450



**Photo #5 Stored unused equipment on side of location.
Appears to be wellhead fence and automation box**



Riser on location not Locked Out and Tagged Out