

Inspection Photos
Operator: SG Interests
Location/API #: 051-06060
Date: 6-19-2019



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View of erosional channeling and unstabilized cut-banks along the access road.



Photo 3. View of more erosional channeling and sediment deposition along the access road.



Photo 4. View of silt trap that is full of sediment.