

# *Inspection Photos*

*Loc#436801*

*Operator: Sandridge*

*Inspection Number: 692401137*

*Inspection Date: 6/26/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to West.

June 26, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Surprise Loc#436801



Photo#2:  
Erosion on Cut Slope.



Photo#3:  
Damaged Wattles at base of Fill Slope.

June 26, 2019





Photo#4:  
Sediment migrating off Site.



Photo#5:  
Compromised Wattle at site perimeter.

June 26, 2019



Photo#6:  
Cuttings pile remains on Southeast Corner of site,  
adjacent to entry.



Photo#7:  
Overview of Location to Southwest.

June 26, 2019