

Interim Reclamation and Stormwater Inspection

July 1, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 434344

Inspection Document #: 697500279

Weld County, CO

SWSW Section 14 T4N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Google Earth aerial imagery taken on 9/12/2018 illustrates that portions of the Production Facility area do not appear to be needed for production operations. Operator shall comply with Rules 1002 and 1003.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 1. Photo taken from the southeastern location, facing West. Site degradation due to erosion was observed along portions of the perimeter of location without stormwater erosion control BMPs.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 2. Photo taken from the southeastern location, facing North. Photo illustrates site degradation along the fill slope without stormwater erosion control BMPs.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 3. Photo taken along the southern location, facing West. See comments under Photo 2.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 4. Photo taken along the southwestern location, facing East. Photo illustrates areas that do not appear to be needed for production operations; however, the Operator has not performed interim reclamation. Also, there was no apparent topsoil stockpile to facilitate future reclamation.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 5. Photo taken along the northeastern location, facing West. See comments under Photo 4.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 6. Photo taken along the northern location, facing East. Photo illustrates unmanaged noxious weeds, Musk thistle.

Inspection Photos

Location Name: No Worries PC /G14-63-1HN Tank

Location ID: 434344



Photo 7. Photo taken from the southeastern location, facing East. See comments under Photo 6.