

# Final Reclamation Inspection

July 1, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 323368

Inspection Document #: 697500283

Weld County, CO

SESE Section 27 T5N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HERBST #27-5  
Location ID: 323368



**Photo 1.** Photo taken from the northern access road, facing South. Operator performed the previous corrective action to perform reclamation along the access road (orange-dashed lines); however, Operator has failed to control and manage a List B Colorado noxious weed, Musk thistle (red circle).



Inspection Photos  
Location Name: HERBST #27-5  
Location ID: 323368



**Photo 2.** Photo taken from a portion of the access road, facing South. See comments under Photo 1.



Inspection Photos  
Location Name: HERBST #27-5  
Location ID: 323368



**Photo 3.** Photo taken from a portion of the access road, facing South. See comments under Photo 1.