

Interim Reclamation and Stormwater Inspection

July 1, 2019

Operator: PDC ENERGY INC - #69175

Location ID: 319511

Inspection Document #: 697500287

Weld County, CO

SWSW Section 7 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 1. Photo taken from the southwestern location, facing North. Operator is in process of responding to the previous corrective action stormwater inspection.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 2. Photo taken from the southwestern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Zeiler /SW-7 Pad
Location ID: 319511



Photo 3. Photo taken from the southwestern location, facing East. See comments under Photo 1.