

Inspection Photos

Location Name: LORENCITO 9-17-34-66

API#: 05-071-06666

INSP. #: 695100976



Colorado Oil & Gas Conservation Commission
37.08219, -104.79806, 2094.0m, 209°
2019/07/08 13:20:41



Colorado Oil & Gas Conservation Commission
37.08218, -104.79804, 2118.0m, 199°
2019/07/08 13:21:18

PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: LORENCITO 9-17-34-66 FOLLOWUP

API#: 05-071-06666

INSP. #: 695100976



PHOTO 3: CORRECTIVE ACTION FROM PREVIOUS INSPECTION DOC# 687900142 EROSION ON ACCESS ROAD NEAR LOCATION HAS BEEN ADDRESSED.

PHOTO 4: CORRECTIVE ACTION FROM PREVIOUS INSPECTION DOC# 687900142 EROSION ON ACCESS ROAD NEAR LOCATION HAS BEEN ADDRESSED.