

Inspection Photos

Location Name: LORENCITO 9-17-34-66

API#: 05-071-06666

INSP. #: 695100976



Colorado Oil & Gas Conservation Commission
37.08219, -104.79806, 2094.0m, 209°
2019/07/08 13:20:41

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.08218, -104.79804, 2118.0m, 199°
2019/07/08 13:21:18

PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: LORENCITO 9-17-34-66

API#: 05-071-06666

INSP. #: 69510097



PHOTO 3: IMPACTED SOIL UNDER PUMPJACK PRIME MOVER. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8/8/19.

PHOTO 4: IMPACTED SOIL UNDER PUMPJACK GEAR BOX. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 8/8/19.