


Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Jun 18, 2019 10:48:29
37.65569N 105.18051W

Spill came from pictured area. Operator state it was a slow leak over a few months. Operator was in the process of updating tank labels at the time of inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Source of leak



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Jun 18, 2019 10:29:37
37.65564N 105.18050W

Source of leak and stained soil.



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Stained soil inside containment.



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Tank label updated.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Source of leak and stained soil.



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Freeboard marker installed



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019



Stained soil in stormwater controls on northwest side of location.



Location Name: Garcia #1-WD API: 055-06012 Inspection Date: 6/18/2019

