

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2019

Submitted Date:

07/09/2019

Document Number:

689703295**FIELD INSPECTION FORM**Loc ID 335435 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262081	WELL	PR	10/19/2002	GW	045-07999	WILLIAMS GM 217-33	PR
262212	WELL	PR	10/19/2002	GW	045-08007	WILLIAMS GM 12-34	PR
262221	WELL	PR	10/19/2002	GW	045-08009	WILLIAMS GM 218-33	PR
298447	WELL	PR	05/31/2009	GW	045-17204	WILLIAMS GM 432-33	PR
298448	WELL	PR	09/22/2008	GW	045-17205	WILLIAMS GM 442-33	PR
298449	WELL	PR	09/22/2008	GW	045-17206	WILLIAMS GM 441-33	PR
298450	WELL	PR	09/22/2008	GW	045-17207	WILLIAMS GM 532-33	PR
298451	WELL	PR	09/22/2008	GW	045-17208	WILLIAMS GM 342-33	PR
298452	WELL	PR	09/22/2008	GW	045-17209	WILLIAMS GM 332-33	PR
298453	WELL	PR	06/03/2009	GW	045-17210	WILLIAMS GM 411-34	PR
298625	WELL	PR	09/26/2008	GW	045-17302	WILLIAMS GM 341-33	PR

General Comment:

On Monday 07/08/19 at approximately 1545 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra GM 217-33, at Location #335435 in Garfield County, Colorado.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	970-285-9377		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	262081	Type:	WELL	API Number:	045-07999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	262212	Type:	WELL	API Number:	045-08007	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	262221	Type:	WELL	API Number:	045-08009	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298447	Type:	WELL	API Number:	045-17204	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298448	Type:	WELL	API Number:	045-17205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298449	Type:	WELL	API Number:	045-17206	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298450	Type:	WELL	API Number:	045-17207	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298451	Type:	WELL	API Number:	045-17208	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	298452	Type:	WELL	API Number:	045-17209	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	298453	Type:	WELL	API Number:	045-17210	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	298625	Type:	WELL	API Number:	045-17302	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689703296	Inspection 689703295 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4871764