

Inspection Photos  
Operator: SG Interests  
Location/API #: 051-06057  
Date: 6-19-2019



Photo 1. View of the northern project area from the northwestern edge facing eastward.





Photo 2. View of erosional channeling and down-cutting along the access road.