

Interim Reclamation and Stormwater Inspection

July 3, 2019

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 416448

Inspection Document #: 697500295

Weld County, CO

NWNW Section 35 T12N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Fox Creek #1-35H
Location ID: 416448



Photo 1. Photo taken from the southern Location, facing North. Photo illustrates sediment discharge off Location along the entire western perimeter. Operator shall take measures to comply with Rule 1004 throughout the impacted areas off Location.

Inspection Photos
Location Name: Fox Creek #1-35H
Location ID: 416448




Photo 2. Photo taken from the southern Location, facing Southwest. See comments under Photo 1.



Photo 3. Photo taken along the western Location, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: Fox Creek #1-35H
Location ID: 416448



Photo 4. Photo taken along the western Location, facing Northwest. See comments under Photo 1.



Photo 5. Photo taken along the western Location, facing Northwest. See comments under Photo 1.