

Inspection Photos  
Location Name: DeVore #2  
Location ID: 332965



Photo 1 WH and WH sign



Photo 2 Crude oil tank.

Inspection Photos  
Location Name: DeVore #2  
Location ID: 332965



Photo 3 separator and ECD



Photo 4 50BBL produced water tank.