

Inspection Photos

07/08/2019

Operator: BISON OIL & GAS II LLC # 10661

Location ID: 455519

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 455519



Photo 1: Photo taken from the east end of the location, facing south. Photos 1-4 provide an overview of the location from south, southwest, northwest to north. Photos show operator has delineated the perimeter of the location in preparation for surface roughening and a perimeter ditch.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 455519



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 455519



Photo 5: Photo taken from the location. Photo shows vegetation prior to disturbance is predominantly smooth brome. Other species observed includes Western Wheat, Buffalo Grass, Sand Dropseed, etc...



Photo 6: Photo of well markers.