

Inspection Photos

07/08/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 422755

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 1: Photo taken from the access road. Photos 1-3 show cattle guards BMPs are filling with sediment. Advise maintenance.

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 3: See comments under photo 1. Photo also shows a patch of Canada thistle along access road and the eastern cattle guard. This is a Colorado State listed noxious weeds and requires management



Photo 4: Photo taken from the east end of the battery. Photo shows stormwater erosion degradation.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 5: Photo taken from the west end of the well location, facing northeast. Photos 5-7 provide an overview of the interim areas and the location from northeast, southeast to south.

Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 7: See comments under photo 5.



Photo 8: Photo shows barrels within secondary containment.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 9: See comments under photo 4



Photo 10: Photo of equipment.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 11: Photo of tank. Two 500 bbl AST, 1 crude, 1 PR water



Photo 12: Photo shows labelling on tanks beginning to fade.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 13: Photo shows labelling on tanks beginning to fade.



Photo 14: Photo of vegetation over the adjacent reference area.

Inspection Photos
Operator Name: NOBLE ENERGY INC - 100322
Location ID: 422755



Photo 7: Photo of the adjacent reference area.