

Inspection Photos

07/08/2019

Operator: BISON OIL & GAS II LLC # 10661

Location ID: 452871

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos

Operator Name: BISON OIL & GAS II LLC # 10661

Location ID: 452871



Photo 1: Photo taken from the southeast corner of the pad, facing southeast. Photo shows erosion degradation along slopes.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 2: Continued from photo 1. Photo shows erosion degradation on slopes and sediment deposition has filled in the stormwater ditch.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 3: Continued from photo 1. Photo shows erosion degradation on slopes and sediment deposition has filled in the stormwater ditch. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 4: Photo taken from the southeast corner of the location, facing northwest. Photo shows erosion degradation on slopes and sediment deposition has filled in the stormwater ditch.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 5: Erosion degradation on the slopes to the south.

Inspection Photos
Operator Name: BISON OIL & GAS II LLC # 10661
Location ID: 452871



Photo 6: Tracking pad at location entrance.