

**Inspection Photos**  
**Location Name: Howard BC A 34-02**  
**Location ID: 327254**




**Photo 1 – Separator, overgrown weeds on the entire location**



**Photo 2 – Tank Battery , overgrown weeds on the entire location. Unused Tank, stairs, and walk over stairs**

**Inspection Photos**  
**Location Name: Howard BC A 34-02**  
**Location ID: 327254**



**Photo 3 – Unused equipment, walkover stairs**



**Photo 4 – Wellhead Sign**



**Inspection Photos**  
**Location Name: Howard BC A 34-02**  
**Location ID: 327254**



**Photo 5 - Weeds at Wellhead**



**Photo 6 – Weeds at Wellhead**

**Inspection Photos**  
**Location Name: Howard BC A 34-02**  
**Location ID: 327254**



**Photo 7 – Unused equipment at Wellhead**