

Inspection Photos
Location Name: Ankeney 2-28
Location ID: 300307



Photo 1 – Tank Battery, inadequate berm height

Photo 2 – Weeds at Separator

Inspection Photos
Location Name: Ankeney 2-28
Location ID: 300307



Photo 3 – Weeds at Tank battery



Photo 4 – Unused Wellhead parts

Inspection Photos
Location Name: Ankeney 2-28
Location ID: 300307



Photo 5 – Unmarked 1” and 2” Risers