

Inspection Photos

Location Name: LORENCITO 7-14-34-67

API#: 05-071-07656

INSP. #: 695100997



PHOTO 1: WELLHEAD/ UNUSED EQUIPMENT (TWO 2" AND ONE 1" RISER). REMOVE UNUSED RISER'S IN ACCORDANCE WITH NTO & RULE 603.f. CA DATE 10/9/19



PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources